



## *Surplus Equipment #2023-2*



### **2015 Chevy Tahoe LT**

- 4x4
- 5.3L V8
- 101000 miles
- Command box and emergency lighting if the purchaser is a public safety agency.
- Needs A/C module replacement. Estimated cost \$2,500
- Needs front-end alignment and new bearing/bushings. Estimated cost \$6,500



## Surplus Equipment #2023-2







*Surplus Equipment #2023-2*







# Surplus Equipment #2023-2





## Surplus Equipment #2023-2







# Surplus Equipment #2023-2





# Surplus Equipment #2023-2







*Surplus Equipment #2023-2*







*Surplus Equipment #2023-2*







*Surplus Equipment #2023-2*







# Surplus Equipment #2023-2








*Surplus Equipment #2023-2*







# Surplus Equipment #2023-2



**GM** MFD BY GENERAL MOTORS LLC 10/14

GVWR	GAWR FRT	GAWR RR
3311 KG	1633 KG	1860 KG
7300 LB	3600 LB	4100 LB

THIS VEHICLE CONFORMS TO ALL APPLICABLE U.S. FEDERAL MOTOR VEHICLE SAFETY STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.

**1GNSK3EC4FR516378** TYPE: M.P.V.

MODEL: K15706

KBFG	TIRE SIZE	SPEED RTG	RIM	COLD TIRE PRESSURE
FRT	P265/65R18	T	18X8.5J	240KPA(35PSI)
RR	P265/65R18	T	18X8.5J	240KPA(35PSI)
SPA	P265/70R17	S	17X7.5J	240KPA(35PSI)

SEE OWNER'S MANUAL FOR MORE INFORMATION.